


Replaces Toro Groundsmaster 5910-D Parts



Rotary Mower - Model 31599 Hydraulic Tank





Replaces Toro Groundsmaster 5910-D Parts



Rotary Mower - Model 31599 Hydraulic Tank

	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
110	Tare No.	rare No.	Description	ricq	Quantity
70	R93-7498	93-7498	Plug-Oil	1	
71	R92-1705	92-1705	Filter-Screen - Hyd Tank	1	
72	R58-4250	58-4250, 99-3497	Catch - Magnetic	1	
73	R2412-108	2412-108, 97406	Clamp - Worm - 1/4 - Stainless	1	
74	R46-6550	46-6550	Fitting - Elbow 90	1	
75	R46-6560	46-6560	Bushing	1	
76	R101526	01-150-0970, 01-178-0620, 20-53-AGD, 321-11, 3224-8, 323-11, 323-12, 323-31, 323-4, 323-4,	Bolt - Hex HD 3/8-16 x 2-1/2 GR5	1	
77	R63-8410	53-6380, 63-4810, 63-8410	Washer - Isolator Bushing	1	
78	R95-6448	95-6448	Spacer	1	
79	R340-136	340-136	O-Ring	1	
80	R105-0131	105-0131	Strainer-Tank - Oil	1	