

Coupling - Compression w/Floloc 1 RG11210





Details

As cap is tightened, pressure causes the gripping ring to bite into the pipe eliminating pull out.

Specifications

Manufacturer Manufacturer's Model No Flo Control 112-10

Amacron Golf & Turf

19 Tate Drive Kerang, 3579 +61 2 8011 1001 Toll Free: 1300 AMACRON https://amacron.rrproducts.com/