



NGK Spark Plug - TR55GP RN3403



Replaces

Autolite	AP5184, AP5243, AP5245, AP605, AP606
Bosch	HR8DPP30V, HR8DPP30Y
Champion	3015, 3015-2, 3401, 3401-2, 3408, 3983, 3983-2, 7015, 7940

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Amacron Golf & Turf

19 Tate Drive Kerang, 3579

+61 2 8011 1001 Toll Free: 1300 AMACRON

<https://amacron.rrproducts.com/>