



NGK Spark Plug - BR6HS

RN3922



Replaces

AC Delco	R42CF, R42F
Autolite	3686
Bosch	WR7A, WR7AC
Champion	830, 931-1, 931M, 931S, 933-1, 933M, 933S, QL7J5, QL82C, QL86, QL86C, RL7J, RL82, RL85, RL86, RL86C
Denso	W20FSR, W20FSRU
R&R Products	R121-0547
Toro	121-0547

Specifications

Manufacturer	NGK
Box Quantity	10
Package Quantity	1

Fits Models

Toro Greensmaster 1000
Toro Greensmaster 1010
Toro Greensmaster 1600
Toro Greensmaster 1610
Toro Greensmaster 800
Toro Greensmaster Flex 1800
Toro Greensmaster Flex 1820
Toro Greensmaster Flex 2100
Toro Greensmaster Flex 2120

Amacron Golf & Turf

19 Tate Drive Kerang, 3579

+61 2 8011 1001 Toll Free: 1300 AMACRON

<https://amacron.rrproducts.com/>