





Replaces Toro Groundsmaster 4000-D Parts



Rotary Mower - Model 30605

Right-Hand & Left-Hand Deck Hydraulics and Discharge
Chambers



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Groundsmaster 4000-D Parts



Rotary Mower - Model 30605

*Right-Hand & Left-Hand Deck Hydraulics and Discharge
Chambers*

Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
Overhaul Kits					
1	R114-5620	114-5620	Seal Kit - Fits R127-3694 Hyd Motor	2	
Hoses					
10	R120-8959	120-8959	Hydraulic Hose Assy	2	
11	R104-2265	104-2265	Hydraulic Hose Assy	2	
12	R132-6116	132-6116	Hydraulic Hose Assy	2	
14	R99-5489	99-5489	Hydraulic Motor	2	
14	R127-3694	127-3694	Hydraulic Motor	2	
Other Parts Available					
16	R104-2204-01	104-2204-01	Inner Chamber Assy	1	
17	R104-2205-01	104-2205-01	Inner Chamber Assy	1	
18	R120-4132-01	120-4132-01	Outer Chamber Assy	1	
19	R104-2203-01	104-2203-01	Outer Chamber Assy	1	
19	R130-2680-01	130-2680-01	Outer Chamber Assy	1	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.