




Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 48in deck - Model 72904
48in Side Discharge Deck



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 48in deck - Model 72904
48in Side Discharge Deck



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|------------------------------|---------------------|---|----------------------------------|---------|----------------|
| Belts | | | | | |
| 20 | R115-7407 | 115-7407 | Belt- V | 1 | |
| Wheels | | | | | |
| 40 | R68-2730 | 1-603299, 68-2730 | Wheel - Anti Scalp | 3 | |
| 41 | R109-9126 | 109-9126 | Tire & Wheel - 13x5.00-6 - White | 2 | |
| 41 | R127-9531 | 127-9531 | Tire & Wheel - 13x5.00-6 - Grey | 2 | |
| Other Parts Available | | | | | |
| 70 | R106-3253-01 | 106-3253-01 | Plate-Hinge, Front | 1 | |
| 71 | R104-8301 | 104-8301, 104-9301, 109-6658, 133-7570 | Locknut - 3/8-16 Nylon Flanged | 33 | |
| 72 | R108-4059-01 | 108-4059-01 | Plate-Hinge, Rear | 1 | |
| 73 | R106-3246-01 | 106-3246-01 | Deflector | 1 | |
| 74 | R151416 | 108-5029, 110-0759, 151416 | Deflector - Long | 1 | |
| 75 | R106-3248-03 | 106-3248-03 | Strap - Discharge | 1 | |
| 76 | R3231-4 | 01-157-0440, 01-173-0612, 3231-4 | Bolt - Carriage 3/8-16 x 1-1/2 | 4 | |
| 77 | R108-2792 | 108-2792 | Rubber Deflector Assy | 1 | |
| 78 | R3296-47 | 3296-47 | Locknut - 5/16-18 Jam Nyloc | 1 | |
| 79 | R108-4052 | 108-4052 | Spring - Torsion | 1 | |
| 80 | R322-50 | 322-50 | Bolt - Hx HD 5/16-18 x 7 1/2 | 1 | |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 48in deck - Model 72904
48in Side Discharge Deck



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|---------|------------------|--|------------------------------|---------|----------------|
| 81 | R98-5967 | 98-5967 | Spacer-Wheel | 1 | |
| 82 | R108-5388 | 108-5388 | Bolt - Hx HD 3/8-16 x 7 1/2 | 1 | |
| 84 | R3231-27 | 3231-27 | Bolt - Carriage 3/8-16 x 7/8 | 2 | |
| 85 | R98-7913 | 98-7913 | Spacer - Tube | 1 | |
| 86 | R98-7912 | 98-7912 | Bushing - Spanner Wheel | 1 | |
| 87 | R323-23 | 01-150-0810, 01-178-0636, 20-60-AGD, 323-23 | Bolt - Hex HD 3/8-16 x 4-1/2 | 1 | |
| 102 | R32128-43 | 30-8990, 32128-43, 3290-357 | Nut - Flanged Whiz - 3/8-16 | 3 | |
| 104 | R112-4212 | 112-4212 | Mount-Pulley | 1 | |
| 105 | R323-11 | 01-150-1440, 01-178-0618, 20-52-AD, 3224-7, 323-11 | Bolt - 3/8-16 x 2 1/4 GR5 | 2 | |
| 106 | R104-0151 | 104-0151 | Spacer | 1 | |
| 107 | R116-6317 | 116-0133, 116-6317 | Spring - Extension | 1 | |
| 108 | R114-5867 | 114-5867 | Anchor - Spring - Tall | 1 | |
| 109 | R109-7952 | 109-7952 | Deck Strut Assy | 2 | |
| 110 | R109-5013 | 109-5013 | Panhard Rod Assy | 1 | |
| 111 | R32128-37 | 32128-37 | Nut - 7-16-14 Hx Serr Fl | 2 | |
| 112 | R116-0886 | 116-0886 | Spring - Extension | 1 | |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 48in deck - Model 72904
48in Side Discharge Deck



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|---------|---------------------|---|--|---------|----------------|
| 113 | R325-17 | 01-150-0640, 01-150-0850, 01-178-0832, 01-178-0836, 20-97-AGD, 325-17, 325-18, 48-9260 | Bolt - Hex Head | 1 | |
| 114 | R3233-34 | 3233-34 | Carriage Bolt - 1/2-13 x 2 1/2 Grade 5 | 3 | |
| 115 | R107-8541-01 | 107-8541-01 | Baffle - Discharge | 1 | |
| 116 | R116-6702-01 | 116-6702-01 | Fork-Caster | 2 | |
| 117 | R3296-51 | 3296-51, 3296-81 | Nut - Nylon Lock 3/4-10 Gr 8 | 2 | |
| 118 | R1-633508 | 1-633508 | Washer - Spring Disc | 6 | |
| 119 | R103-0063 | 103-0063 | Seal - Grease | 4 | |
| 120 | R325-42 | 325-42 | Bolt - 1/2-13 x 8 Hex Head Gr 5 | 2 | |
| 121 | R103-2768 | 103-2768 | Guard - Seal | 4 | |
| 122 | R103-3051 | 103-3051 | Spacer - Nut - Hardened | 4 | |
| 123 | RF5003 | 32127-29, 32131-5, 32132-5, 3296-23 | Locknut - ESNA 1/2-13 | 2 | |
| 124 | R126-5360 | 126-5360 | Axle- Caster w/Spacer Nut | 2 | |
| 125 | R116-0797-03 | 116-0797-03 | Link-Lift - Deck | 1 | |
| 126 | R116-0780 | 116-0780 | Bolt - Hx HD Fl Shoulder | 2 | |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 48in deck - Model 72904
48in Side Discharge Deck



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|---------|------------------|---|-------------------------------|---------|----------------|
| 127 | R453022 | 01-166-0480, 01-166-1220, 21-3880, 217-21, 30-8550, 30-9110, 3256-28, 3256-44, 46-9030, Mar-71 | Washer - 3/4 SAE | 2 | |
| 128 | R32128-23 | 32128-23, 3218-23, 99-5107 | Nut - Lock Hex Flanged 1/2-13 | 8 | |
| 129 | R109-5010 | 109-5010 | Spacer | 6 | |
| 130 | R109-5009 | 109-5009 | Bushing - Suspension - Rubber | 6 | |
| 131 | R325-12 | 01-150-0320, 01-150-0880, 01-178-0824, 20-93-AD, 325-12 | Bolt - Hx HD | 1 | |
| 132 | R116-5647 | 116-5647 | Seal - Grease | 2 | |
| 133 | R254-94 | 1-543509, 254-94, 32-8090, 32-8240, 32-9640, 40440, 62-3330 | Tapered Bearing Cone | 4 | |
| 135 | R254-78 | 01-102-0060, 01-102-0130, 1-633585, 254-78, 32-7790, 32-9580, 93-4813 | Tapered Bearing Cone | 4 | |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 48in deck - Model 72904
48in Side Discharge Deck



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|---------|---------------------|--|------------------------------|---------|----------------|
| 136 | R254-72 | 01-103-0050, 01-103-0120, 01-103-0140, 1-543508, 254-71, 254-72, 40439, 62-3340, 99-4511 | Cup - Bearing | 4 | |
| 137 | R121-7975-01 | 121-7975-01 | Plate - Skid | 1 | |
| 140 | R114-5862-01 | 114-5862-01 | Baffle | 1 | |
| 141 | R116-0459-03 | 116-0459-03 | Lift - Rear Deck | 1 | |
| 142 | R114-5870 | 114-5870 | Idler Arm Assy with Bushings | 1 | |
| 143 | R1-303514 | 1-303514 | Bearing - Flanged | 2 | |
| 144 | R109-9066 | 109-9066 | Yoke - Adjust - Deck | 4 | |
| 145 | R103-4882 | 103-4882 | Grease Cap - Castor | 2 | |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.