



# 1 PVC Union Split Nut Kit

RGSNK010



## Details

Split Nut Repair Kit is designed to replace broken union nuts on all True Union 2000 Ball Valves and Sch 80 Union 2000 fittings.

Kit includes: 2-Split Nut Halves 1-SS316 Gear Clamp.  
Full valve pressure rating maintained.

## Specifications

Manufacturer	Spears
Fitting Size	1



## Amacron Golf & Turf

19 Tate Drive Kerang, 3579

+61 2 8011 1001 Toll Free: 1300 AMACRON

<https://amacron.rrproducts.com/>